


Derelict park features

1) Bandstand



The bandstand is structurally sound, but its roof leaks badly. Most of the paintwork on the metalwork has peeled off and the wrought iron is beginning to rust. The concrete base and surrounding area is severely cracked and needs resurfacing.

- Estimated cost to repair bandstand: £20,000.
- Estimated cost to replace ground surface: £10,000 - £50,000 depending upon material used.